

Annex 4: selected photographs from Šebrov and Svatá Kateřina. At notable road safety issues, comments are added.



*Entry to Šebrov – only the speed limit symbol is not enough to calm all the cars driving in.*



*Šebrov – driver's sight at the intersection; looking to the right, the sight is not sufficient.*



*Narrow pavement in Šebrov – one can imagine that the pram cannot go through without entering the road.*



*Šebrov – excessive comfort in the road width. Nevertheless, shoulders are not wide enough either for cycle lane or parking lane.*



*The bus stop in Šebrov – standing bus creates queues, sometimes even with illegal overtaking. There is also pedestrian crossing missing – people are used to cross the road even without it.*





*Šebrov – going downhill to the large intersection with the main road without channeling the lanes or directions.*



*Pedestrian crossing in front of elementary school with insufficient road signing and marking – both the warning sign on the right and the symbol on the ground are hardly visible.*



*Šebrov – two examples of lines of sight, obstructed by the vegetation.*





*Svatá Kateřina – the state of the road and road marking is apparently poor.*



*Road signs indicate the risk and order to slow down without any evident reason – the road is not self-explaining.*



*Entering the intersection in Svatá Kateřina – the priority sign is hidden in the vegetation. The sight is also not sufficient.*





*Not just that road marking is poor, it is also misleading: double line? dashed line? full line?*